

J.B.S. Jr
OK-AD-



Sec. 35

3955 Ophir Mountain Cons Quartz Mine

The above diagram of Section 35, Township No 5 North,
Range No 11 East, Mount Diablo Meridian, California
is correctly constructed from official plats on file in
this office.
U.S. Surveyor General's Office
San Francisco California
May 2nd 1901

J. M. Gleaves,
U.S. Surveyor General
for California.



No. 72 A. McKinney & Crannis Quartz Mine } V-8-6
No. 72 B. " " " Mill Site }

The above diagram showing amendments to Sections 10 & 15, Township No.5 North, Range No.17 East, Mount Diablo Meridian, is correctly copied from the original map as amended and on file in this Office.

U.S. Surveyor General's Office
San Francisco California
March 17th 1884

W. F. Brown
U.S. Surv. Genl. Cal.



2484-76. Finck Gold Quartz Mine 179-25

The above diagram showing amendments to Secs 34 & 35 Township No 35 North Range No 11 East, Mount Diablo Meridian, is correctly copied from the original map as amended and an file in this office
U.S. Surveyor General's Office
San Francisco California,
September 7th 1896.

R B Hammond Jr
U.S. Surg. Genl. Col.



Lot No. 70 Oneto Quartz Mine. V-9-12
" " 71 Borattini " 197-13

DEPARTMENT OF THE INTERIOR,
GENERAL LAND OFFICE,
Washington, D. C. *Jan 11* 1908:
I hereby certify that this is a true copy
of the plats of official survey of the lands
to which it relates, on file in this office.

H. G. Long
Recorder, General Land Office.

The above diagram showing amendments to Sec. 15 Township 16 S North,
Range No. 11 E East, Mount Diablo Meridian, is correctly copied from the
original map as amended and on file in this office.
U.S. Surveyor General's Office
San Francisco California
March 4th 1896.

41 420

W. H. Brown
U.S. Surv. Genl. Gato.

CHAINS

CHAINS

10 20 40 60 80 120

B-LM 233

TENRILEAD